

Post Site Inspection

Site Name: NORTH SHORE MATERIALS I.N. Number FILE 0489 SL

Date of Inspection: 5-7-87

Was Work Plan Followed
If no, explain briefly:

Y

N

EPA Region 5 Records Ctr.



357448

Were Samples Collected?
Residential Wells Sampled?

Y

N
N

Y

Anticipated Analysis Report From:

CRL _____

CLP _____

Anticipated SI Completion: 14 DAYS (5-21-87)

Removal Investigation Recommended
If yes, explain briefly:

Y

N

Unanticipated Problems Encountered
If yes, explain briefly:

Y

N

Follow-up site work necessary
If yes, explain briefly:

Y

N